

WATER DEPARTMENT REPORT

November 10, 2014

ACCOMPLISHMENTS:

- All bacteriological samples from Field St Well came back negative
- Pioneer Motors was here and installed new soft start controller for the new Well. Everything works and is ready to go.
- Took 2 bacteriological samples from the new East side tank. All samples were good. Thank you to the Proctor Fire Department for their help filling the tank
- Belden here to fix a water leak on Ormsbee Ave
- Worked with VRWA doing leak detection. We found a sizable leak in the Marble yard that is scheduled to be investigated in confined space and / repaired.
- Located utilities near the marble yard for GMP. They set 3 new poles in the area
- Meet with Ray Solomon from the State, Aaron Perez from VRWA, and our engineer at Field St well to discuss chemical feed dose rates
- Bumper crane to be installed on the F350 Thursday, Nov 13th
- Phone and internet installed at Field St Well building
- Worked with the HW Dept cleaning and organizing the Water/ Sewer garage bay
- have checked numerous areas for leaking valves or suspected areas for broken mains
- Responded to leaking valves on Park St (Outslay's yard) exercised. Appears to have slowed / stopped leaking.

NEEDED:

- Direction from the board to have the overflow pipe fixed at the West Side Tank. It is broken at the top invert